

# Bruce Baker Enterprises, Inc.

Restoration and Porsche® Specialist

7 Crosskeys Road

Collegeville, PA 19426

610-831-1200 Fax: 610-831-1205

E-mail: [bbspdstr@aol.com](mailto:bbspdstr@aol.com)

[www.356restoration.com](http://www.356restoration.com) or [www.bbakerent.com](http://www.bbakerent.com)

June 9, 2015

Robert Boyle

4 Willow Avenue

North Hampton, NH 03862

603 397 3700 (Office)

603 379 2265 (Home)

973 214 3626 (Cell)

Subject: 1959 Porsche 356A Cabriolet, VIN 151896

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
<i>Labor last billed 11/22/2013</i>							
1/23/14	Sand primer, straighten front bumper, sand steering column and parts, prime and paint	3.5	\$ 280.00				
2/3/14	Wiring, solder break on steering shaft, rebuild washer pump, install W/S/W hose	4.0	320.00				
2/5/14	Re-prime bumper, spray support tubes with silver, begin clutch cable installation with new parts	2.0	160.00				

<b>Date</b>	<b>Labor</b>	<b>Hours</b>	<b>Labor Cost</b>	<b>Parts</b>	<b>Parts Cost</b>	<b>Credit</b>	<b>Total</b>
2/6/14	Bumper details and adjustments, install rear shocks, assemble many small items and make brackets, re-aim clutch cable outlet tube, install heater cans and other underside details (2 techs)	6.0	480.00				
2/10/14	Polish black paint on front bumper, install brackets and place on car temporarily	1.75	140.00				
2/17/14	Remove shell from chassis dolly, ready engine, install front sway bar and steering dampener, check fasteners and lines, wiring and assembly details	6.75	540.00				
2/18/14	Clean flywheel, re-route wires and better rounds, fit rocker decos and drill holes, grease front suspension and steering, install glove box parts, grab handle, etc.	5.0	400.00				
2/19/14	Assemble rear bumper, install license bracket, miscellaneous wiring, instrument installation, drill for and install Tenax studs for boot, deco and miscellaneous assembly	7.5	600.00				
2/20/14	Bumper and miscellaneous detail assembly (2 techs)	8.0	640.00				
3/6/14	Engine prep for installation, make fuel line bracket on fan tin, carb control rods, install new lower case studs, tap / chase threads, add fuel lines	4.5	360.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
3/11/14	Install new oil senders, fabricate extension for dual oil pressure sender	3.5	280.00				
3/13/14	Wiring behind dash, add grommet for speed cable in left axle	1.5	120.00				
3/15/14	Fill trans, add 12V voltage regulator	1.0	80.00				
5/12/14	Fit replacement parts, re-order missing parts, install parts (miscellaneous)	1.25	100.00				
5/21/14	Add fresh gas, reconditioned parts, paint details, final assembly in engine compartment	3.5	280.00				
6/4/14	Install heater cables, add proper wires from generator to volt regulator	2.5	200.00				
6/10/14	Miscellaneous assembly, shifter, check underside shims and gearbox alignment	.75	60.00				
6/11/14	Finish engine wiring at rear	1.25	100.00				
6/19/14	Connect fuel and throttles systems (2 techs)	3.0	240.00				
7/2/14	Assemble parts on dash and underneath, add door hinge cover plaques and radio blank-off plate, luggage loops, brake check, add fluid (2 techs)	3.0	240.00				
7/15/14	Light check, fuss with seat tracks, locate odd hardware, miscellaneous assembly	4.0	320.00				
7/17/14	Adjust and re-bleed air from brakes, tighten exhaust and clamps, funnels, clean interior pre-carpet installation	2.5	200.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
7/25/14	Re-check all lines and fittings on brakes and underside	.5	40.00				
7/29/14	Re-gasket and seal oil pump cover	0	0				
7/31/14	Check fuel system, rotate fuel valve, outlet, add trans oil (top off) find better air cleaner can and prep	3.5	280.00				
8/4/14	Reposition carpet under threshold strip, install ashtray, find replacements for missing top frame hardware	2.5	200.00				
8/12/14	Clean external parts and store	0	0				
8/22/14	Pick-up engine in VA at Eric Wills' shop in VA	0	0				
11/20/14	Help Jim Q with top frame	.5	40.00				
12/11/14	Install throttle rod boot, hand-brake hanger, adjust shifter lever and heater cables	3.0	240.00				
12/12/14	Adjust hood latch, dress new seal, lube	1.0	80.00				
12/30/14	Reconnect engine and underside parts	0	0				
12/31/14	Continued connections for motor and dash, underside adjustments	3.5	280.00				
1/16/15	Straighten and polish trim for top at door glass, fit rubber seals and channels, windshield	2.0	160.00				
1/17/15	Continued fitting channels and seals	.5	40.00				
1/22/15	Continued with rubber seals, adjust glass	2.0	160.00				
2/2/15	Continued assembly, trim and rubber	5.25	420.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
2/3/15	Fasten top latches, finish door window track adjustments, door seals	4.5	360.00				
3/9/15	Install and adjust seats and tracks, lube	2.25	180.00				
3/10/15	Re-check several dash leads, shim seat risers and tracks to parallel, light check, clean and re-blacken floor inside	7.0	560.00				
3/12/15	Install right side fender badge, cleaning, check lubes and fluids	1.5	120.00				
3/24/15	Lube pedal cluster, clutch cables and arms, e-brake, adjust shoes	2.0	160.00				
3/25/15	Re-do seat bottom rails for better alignment, send seat bottom back to trimmer	0	0				
4/20/15	Re-route tach cable, lube heat control wires, reposition ignition switch, check oil and test run engine	2.25	180.00				
4/22/15	Adjust brakes, lube shifter, mount license plates	3.0	240.00				
4/23/15	Adjust steering column and wires, add light switches at door hinges, Siamese wires for high beam and horn, paint touch-up and polish	4.25	340.00				
4/24/15	Adjust front bumper, add brakes and grommets, clean and lube, add gold emblem to front	2.0	160.00				
4/27/15	Paint and assemble wiper arms and blades	1.0	80.00				

<b>Date</b>	<b>Labor</b>	<b>Hours</b>	<b>Labor Cost</b>	<b>Parts</b>	<b>Parts Cost</b>	<b>Credit</b>	<b>Total</b>
4/28/15	Install and test wipers, adjust door latch, polish dash	1.0	80.00				
4/29/15	Finish bumper details and visual appearance, clean and polish	1.0	80.00				
4/30/15	Polish, add trim strip on top (second try)	4.5	360.00				
5/5/15	Install seat belts, rear seat bungee	1.5	120.00				
5/6/15	Reset ride height on rear left, fit new rubber floor mats, add snaps, trim and add holes as needed (2 techs)	6.0	480.00				
5/8/15	Alignment, adjust front ride height, test drive, adjust hood latch and replace pull wire	4.5	360.00				
5/11/15	Polish, finish underside details, add new hardware as needed	3.75	300.00				
5/12/15	Adjust bearings and link pins on front end while on lift, clean deco strips, align 4 wheels	2.25	180.00				
5/14/15	Clean and polish hood, fenders, engine, lower body, trunk	4.0	320.00				
5/15/15	Add grease to front torsion bar tubes, change seat belts, grind limiting bolt on right front, replace battery and cover	3.5	280.00				
5/18/15	Repair old horn relay and wiring	2.0	160.00				
5/19/15	Readjust shifter, replace conical bolt at trans, torque lug nuts and install hub caps	2.0	160.00				

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
5/21/15	Finish blackening and protecting bolts, trim fasteners in engine bay install air cleaners, test drive	<u>2.5</u>	<u>200.00</u>				
	<i>Total labor</i>	169.25					\$13,540.00
				Horn contact assembly ('button') 644-347-821-01	\$369.00		
				"A" horn cancelling ring 644-613-325-00 (new)	45.76		
				"A" owner's manual cover	22.43		
				"A" owner's manual (repro)	147.87		
				(2) wide aluminum carpet strips @\$13.50/ea	27.00		
				Screw set for above	8.63		
				(2) bronze bell crank bushings @\$6.50/ea	13.00		
				(2) air cleaner decals @\$4.46/ea	8.92		
				Rear seat bungee with kit	129.15		
				(2) window channels @\$14.35/ea	28.70		
				Rear wood top bow	194.50		
				(2) new seat adjuster springs @\$3.90/ea	7.80		
				(10) Tenax studs and plastic washers (top for boot) @\$6.00/ea	60.00		
				Miscellaneous shop materials (paints, solvents, polishes, etc.)	75.00		
				(8) special (and hard to find) shim washers for vent window locks @\$2.00/ea	16.00		
				New clutch cable 644-432-401-00	22.94		

Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				New sheath / housing NLA-23-209	26.41		
				(2) hold-downs for rear top lower bow @\$28.00/ea	96.00		
				(2) new glass headlight lenses, Porsche supplied, @\$135.90/ea	271.80		
				(2) better rocker decos @\$76.50/ea	153.00		
				(2) better rubber inserts @\$13.60/ea	27.20		
				Seat rail set	173.11		
				(24) T-studs for rockers (Porsche) @\$3.85/ea	92.40		
				Glove box lock (new)	65.75		
				Better front rubber mat	317.05		
				Better rear mats (set)	210.68		
				Better tunnel mat	180.78		
				Additional shop materials (glues, solvents, tape, etc.)	50.00		
				(3) new top latches - stainless @\$95.00/ea	285.00		
				(96) pieces of metric hardware @\$0.50/ea	46.50		
				Gear lube additive, Lucas	28.00		
				Original appearing rectangular 12V voltage regulator (at cost, with core)	400.00		
				Engine oil console nut, new, for stacking	15.26		
				Stainless steel hardware (at cost)	9.00		
				Additional Bright zinc plating charge, batch (at cost)	125.00		



Date	Labor	Hours	Labor Cost	Parts	Parts Cost	Credit	Total
				Interstate MT-26 battery (12V) with core (at cost)	83.95		
				Fuel (10) galls @\$3.00/ea	30.00		
				Engine oil (4) quarts @\$4.69/ea (second change)	18.76		
				Throttle rod boot	7.56		
				Top-to-windshield frame seal	<u>17.74</u>		
							<u>3,907.63</u>
							\$17,447.63
	Remainder, bill of 2/5/2014						<u>29,113.36</u>
							\$46,560.99
	<i>Credits:</i>						
	Paypay 2/12/2014					\$10,000.00	
	Paypal 2/18/2014					5,000.00	
	Direct deposit 3/25/2014					15,000.00	
	Direct deposit 3/27/2014					<u>1,000.00</u>	
							<u>31,000.00</u>
							<b>\$15,560.99</b>