

Bruce Baker Enterprises, Inc.

Restoration and Porsche® Specialist
 7 Crosskeys Road
 Collegeville, PA 19426
 610-831-1200 Fax: 610-831-1205
 E-mail: bbspdstr@aol.com
www.356restoration.com or www.bbakerent.com

Robert Boyle
 4 Willow Avenue
 North Hampton, NH 03862
 603-397-3700 (Office)
 603-379-2265 (Home)
 973-214-3626 (Cell)

August 3, 2013

Subject: 1959 Porsche 356A Cabriolet, VIN 151896

| Date | Labor | Hours | Labor Cost | Parts | Parts Cost | Credit | Total |
|--|--|-------|------------|-------|------------|--------|-------|
| <i>Last billing through May 21, 2013</i> | | | | | | | |
| 6/11/13 | Prepare added suspension parts for black urethane paint, install new rear wiring prior to trans installation, re-drill rear tunnel access for brake line, rebuild steering knuckles, link and kingpins, bushings, remove cockpit brace (2 techs) | 8.0 | \$ 640.00 | | | | |
| 6/12/13 | Paint brake parts with urethane, clean and sand exterior of shell | 1.5 | 120.00 | | | | |
| 6/14/13 | Box painted parts, store, continue with bodywork | 1.5 | 120.00 | | | | |
| 7/11/13 | Adjust doors after loading appropriate weight in areas of shell, sand primer, prep for lead work | 8.25 | 660.00 | | | | |

| Date | Labor | Hours | Labor Cost | Parts | Parts Cost | Credit | Total |
|---------|--|------------|--------------|--|----------------|--------|------------|
| 7/15/13 | Right side bodywork, door fender and quarter panel | 8.5 | 680.00 | | | | |
| 7/16/13 | Right side lock post, inner edges of door, fender, block sand | 9.0 | 720.00 | | | | |
| 7/17/13 | Trial fit door glass and chrome, vents, frames, top frame fit | 9.5 | 760.00 | | | | |
| 7/18/13 | Left side bodywork, miscellaneous details, gaps, jambs, contours | 9.0 | 720.00 | | | | |
| 7/19/13 | Miscellaneous bodywork, sanding | 4.0 | 320.00 | | | | |
| 7/2/13 | Bodywork, hood and front end | 4.0 | 320.00 | | | | |
| 7/22/13 | Smooth hood, fenders, nose, gaps, ready for primer, mask | 9.0 | 720.00 | | | | |
| 7/23/13 | Weld crooked holes for front gold emblem, smooth right fender, even gaps | 9.5 | 760.00 | | | | |
| 7/25/13 | Sand primer, clean car and surrounding area, remount center brace and reset on dolly (on suspension) | 3.5 | 280.00 | | | | |
| 7/26/13 | Weld closed unneeded gauge holes on dash, grind, clean | 1.75 | 140.00 | | | | |
| 7/30/13 | Blast, wire-brush suspension hardware for plating | <u>.75</u> | <u>60.00</u> | | | | |
| | <i>Labor sub-total</i> | 87.75 | | | | | \$7,020.00 |
| | | | | Black urethane paint mix (leftovers), 6 sticks of lead | N/C | | |
| | | | | Black Aerosol etch primer (11) additional aerosol gum cutters ("2+2") @\$4.49/ea | 14.00 49.39 | | |
| | | | | Würth Contact OL | 12.75 | | |
| | | | | Good used door handle spring | 3.50 | | |

| Date | Labor | Hours | Labor Cost | Parts | Parts Cost | Credit | Total |
|------|-------|-------|------------|--|------------|--------|-------|
| | | | | Flexible disc | 3.78 | | |
| | | | | (6) rubber plugs and grommets for brake and fuel lines @\$4.58/ea | 27.48 | | |
| | | | | (86) pieces of metric hardware | 43.00 | | |
| | | | | (6) aerosol primers @\$11.50/ea | 69.00 | | |
| | | | | (4) aerosol cans of enamel paint @\$4.29/ea | 17.16 | | |
| | | | | (2) 3M Kleen-N-Strip abrasive discs @\$8.29/ea | 16.58 | | |
| | | | | (6) 3" 3m thin cutting discs @\$5.45/ea | 32.70 | | |
| | | | | (3) Roloc discs @\$4.29/ea | 12.87 | | |
| | | | | (3) 3M 1/4" grinding discs @\$5.85/ea | 17.55 | | |
| | | | | (Qt) epoxy primer (A+B) @\$48.00/ea | 96.00 | | |
| | | | | Additional blasting supplies (glass beads, aluminum oxide, expensive nozzle) | 100.00 | | |
| | | | | (11) 13" x 3/8" sanding belts @\$3.29/ea | 36.19 | | |
| | | | | Rear transmission rubber mounts (set) | 211.40 | | |
| | | | | (4) rear torsion bar end grommets @\$14.80 | 59.20 | | |
| | | | | Quart, All-Metal epoxy filler at cost | 36.41 | | |
| | | | | Miscellaneous shop supplies (solvents, tape, sandpaper) | 106.60 | | |
| | | | | Norton (sticky-back) discs, box | 48.25 | | |

| Date | Labor | Hours | Labor Cost | Parts | Parts Cost | Credit | Total |
|------|----------------------------------|-------|------------|--|---------------|--------|------------------|
| | | | | Re-plating of original hardware for suspension | 125.00 | | |
| | | | | 904 combination gauge w/senders, at cost | 558.00 | | |
| | | | | Reconditioned 200mm flywheel, including shipping to Meister Resto. | <u>675.00</u> | | |
| | | | | <i>Parts sub-total</i> | | | <u>2,371.81</u> |
| | <i>Sub-total</i> | | | | | | \$ 9,391.81 |
| | Due from bill of 6/10/13 | | | | | | <u>1,148.89</u> |
| | <i>Sub-total</i> | | | | | | \$10,540.70 |
| | Credit of direct deposit 6/12/13 | | | | | | -10,000.00 |
| | TOTAL DUE | | | | | | \$ 540.70 |